




Title			CONNECTOR_1_V4B
Size	Number	Revision	
A4	NO.2		
Date:	9-Jan-2004	Sheet	of
File:	E:\project\sc20\version4B\sc20_main4B.d	Drawn By:	





Title			AUDIO_TEST_V4B		
Size	Number		Revision		
A4	NO.3				
Date:	6-Jan-2004		Sheet of		
File:	E:\project\sc20\version4B\sc20_main4B.dld		Drawn By:		







Title			KEYBOARD_V4B		
Size	Number		Revision		
A4	NO.4				
Date:	6-Jan-2004		Sheet	of	
File:	E:\project\sc20\version4B\sc20_main4B.d		Drawn By:		




Title		
CONNECTOR_2_V4B		
Size	Number	Revision
B	NO.5	
Date:	6-Jan-2004	Sheet of
File:	E:\project\sc20\version4B\sc20_main4B.dwg	Drawn By:



Title			DETECT_V4B
Size	Number	Revision	
B	NO.6		
Date:	6-Jan-2004	Sheet of	
File:	E:\project\sc20\version4B\sc20_main4B.d	Drawn By:	



Title			POWER_V4B		
Size	Number		Revision		
A4	NO. 8				
Date:	6-Jan-2004		Sheet	of	
File:	E:\project\sc20\version4B\sc20_main4B.d		Drawn By:		



sc20 version4B

after modification there are ☐
no c720 and c721 just ☐
VR701 and VR702

040319

here need remove
3 pcs 18pF

040319

